



**RECEIVED**

By Recall Mangement Division at 7:55 am, Aug 01, 2014

Ms. Sarah McShane  
Safety Recall Analyst, Recall Management Division  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue SE, Room W46-419  
Washington, DC 20590

July 31, 2014

Dear Ms. McShane

This letter is written in response to your request of July 22 for the information missing from Mazda's revised notification letter submitted on June 20 for recall 14V-344 (Regional Recall for Takata airbag inflators).

The following list shows each model and the number of affected vehicles for each subject air bag (driver's side air bag, passenger's side air bag, or both). We are still reviewing the information for the Mazda6 and will provide that information as soon as it is available.

Also we have identified that the 2004 MY Mazda B-Series, which was produced by Ford Motor Company, is to be included in this action, so we are providing the information for the B-Series below. We had not identified the B-Series in our original list of affected vehicles.

Model	The subject air bag			Total	VIN range	Part number of passenger's air bag inflator	Part number of driver's air bag inflator
	Passenger's air bag only.	Both airbags	Driver's air bag only.				
RX-8	3,028	1,499	3,632	8,159	JM1FE1***** 100063-214178	GKYA57K80	FEY157K80
Mazdaspeed6			641	641	JM1GG1***** 100133-110732	GKYA57K80	GJYA57K80
MPV	2,139			2,139	JM3LW2***** 500024-532952	GKYA57K80	GJYA57K80
Mazda6	Under review.					GKYA57K80	GJYA57K80
B-series	1,807			1,807	4F4YR***** M00075-M13004	Under review	
	258			258	4F4ZR***** M00472-M12624		
Temporary Total	7,232	1,499	4,273	13,004			

If you have any further questions, please let me know.

Sincerely,

David Robertson, Group Manager  
Product Engineering Group 1  
Mazda North American Operations  
248-295-7859